Diagnosis report of **2015 PEUGEOT 308 Executive**



Car Details

Color: Blue	CO ₂ NEDC Emission: 82 g/km	
Fuel Type: Diesel	CO ₂ WLTP Emission: 0	
Body Type: Hatchback	Low CO_2 Emissions: Yes	
Number Of Doors: 4	Engine size: 1.6 l	
Number Of Seats: 5	Cylinders: 4	
Mileage: 240 731 km	Power: 88 kw, 120 Hp	
VIN Code: VF3LBBHZHFS209794	Fuel Consumption: 3.1 I/100km	
Gearbox: Manual	Tire size: 205/55 16	
Drive type: FWD	Longo Stock ID: N941388	
Next technical inspection date:		

🕵 Longo Certified

Car photos



Diagnosis report of **2015 PEUGEOT 308 Executive**



Diagnosis details

Date of completion: 23.04.2024

Mileage on completion date: 240 731 km

Checked by Longo Shared Service certified diagnostics: Arnas S., A. R.

This car has been thoroughly checked according to **Longo 150-point checklist** which covers Body exterior, Interior, and Mechanical condition. We can confirm that it has never been involved in major accidents and has had regular maintenance, as well as mandatory roadworthiness tests in the country of export.

Please note that certain general wear and tear issues are considered acceptable and may not be repaired.

Summary of diagnosed issues

During the comprehensive diagnosis conducted by Longo, 16 issues were identified in the vehicle. 10 of these issues were rectified. 6 of the diagnosed issues are deemed to be fair wear and tear.

INTERIOR	EXTERIOR	MECHANICAL
2 issues rectified2 fair wear and tear	1 issue rectified4 fair wear and tear	7 issues rectified

Diagnosis process

Diagnosed issues repaired


- iongo

Interior

- 1. SEATS: All seats condition
 - Sew front seat



2. INSIDE: Carpets - condition



Exterior

- 1. LIGHTS: Rear lights (brake, fog, indicator) basic functioning, damage, color
 - Change rear lights



Mechanical

1. OTHER:

Engine camshaft repair "sandwich"

2. OTHER:

Sengine oil & filter change

3. OTHER:

Change tyres

4. ENGINE:

Camshaft/valve cover & gasket



5. ENGINE:

AD blue injector



6. EXHAUST SYSTEM:

Pipe - middle/silencer



7. GENERAL ELECTRICS:

Battery

Fair wear and tear

- Longo

Interior

1. SEATS: All seats - condition



2. INSIDE: Trims - condition



Exterior

1. REAR: Rear bumper - condition and alignment



2. FRONT: Integrity of engine cover



3. FRONT: Hood - visual damage



4. SIDE: Left and right side - visual damage / scratches



Longo 150-point checklist



Every vehicle is carefully examined according to Longo's comprehensive 150-point checklist, ensuring a thorough assessment of the car's interior, exterior, and mechanical condition. Depending on the factors such as condition, mileage, and specifications, additional checks may be included or certain points from the list may be omitted.

Record the fuel type Record the transmission type A. Record the registration number S. Record the VIN number A. Record the mileage	 52. Check AdBlue level and add if necessary (only for diesel cars) 53. Check AdBlue level and add if necessary (only for diesel cars) 54. Check key - functioning and condition 	 102. Check timing belt or chain for integrity 103. Check timing belt or chain for any audible signs of problems (start & while idling) 104. Check for any signs of leakage of any liquids
4. Record the registration number 5. Record the VIN number	54. Check key - functioning and condition	while idling)
5. Record the VIN number	· -	104. Check for any signs of leakage of any liquids
6. Record the mileage	55. Check passenger chair airbag setting and reset to default	105. Check level of coolant or anti-freeze in the tank
	56. Dashboard - condition; operation of buttons	106. Add coolant if necessary
7. Record the year the car was manufactured	57. Steering wheel - condition	107. Check if coolant tank is filled with anti-freeze
8. Record the date of first registration	58. Steering wheel - operation of controls/buttons	108. Ensure engine cooling system is free of visual contamination
9. Record the date/mileage of the last service	59. Car horn - operation	109. Check quality of brake fluid using the testing pen
10. Record the date/mileage of the next service due	60. Window wipers (front & rear) - functioning	110. Check the level of brake fluid
11. Check car's maintenance history and manufacturer recall and safety campaigns	61. Window wash system - functioning (front & rear)	111. Check powersteering fluid color (if dark, replace)
12. Front lights (city, regular and full headlight, fog, indicator) - functioning & condition	62. Rearview mirror - operation and integrity of attachment	112. Check powersteering fluid level
13. Front light height adjustment system - functioning & condition	63. Sunvisors - operation and condition	113. Check oil level
14. Lights on car sides - functioning & condition	64. Rearview mirror - operation and integrity of attachment	114. Check if tyres are properly fitted (should be fitted in driving direction
15. Rear lights (brake, fog, indicator) - functioning & condition	65. Headlining - condition	115. Check tyre profile
16. Numberplate lighting system - functioning & condition	66. Roof items - electronic opening and condition	116. Check tyre pressure
201 Kamber plate lighting of stelling interestioning of condition	of Root Rents' cleen one opening and contactor	117. Check the additional set of tyres - check for any signs of cracks due to
17. Rear reflectors - condition	67. Navigation and radio system - operation	dehydration (if there is an additional set of tyres)
 Windscreen integrity - free from any damage that would exclude the vehicle from MOT test 	68. Rear view camera / proximity sensors - functioning	118. Check additional set of tires - Check tire profile (if there is additional set of tires)
19. Windscreen windows wiper rubbers and handles - condition	69. Parking assistance systems - functioning	119. Check the wheels for proper attachment (all bolts present and with correct tension)
20. Front bumper - condition and alignment	70. 12-volt and USB connectors - functioning	120. Check the integrity and proper attachment of drivetrain system
21. Front grill - condition	71. Heating system - functioning	121. Check the drivetrain attachment to engine for potential leaks
22. Hood - visual damage	72. Aircon system - functioning	122. Check the integrity and the proper attachment of the wheelhouse
23. Hood opening & holding mechanism	73. Window heating mechanism - functioning (front & rear)	123. Check the wheelhouse for potential leaks
24. Hood sound insulation for condition	74. Seat heating system - functioning (driver & passenger)	124. Check for sings of slack while turning wheels to extreme position
25. Fire wall for condition	75. Seatbelts - functioning and locking mechanism	125. Check the brake disks for integrity and potential oxidation
26. Window washer fluid level (and adequate winter washer fluid)	76. Seat adjustment mechanisms - functioning (driver & passenger)	126. Check the brake pads for integrity and proper attachment
27. Integrity of front subframe	77. All seats - condition	127. Check the brake pads for thickness
28. Rear window integrity	78. Door handles - operation and condition	128. Check the integrity of brake hoses (signs of cracks from dehydration, misshaping and leakages)
29. Rear windows wiper rubber and handle	79. Electronic opening of all windows - functioning	129. Check the integrity of brake pipes (oxydation, misshaping and leakages)
30. Rear bumper - condition and alignment	80. Exterior side mirrors - electronic mirror controls, folding and adjustment mechanism	130. IF FITTED: check the brake drums for audible signs of any issues whil turning the wheels
31. Tow hitch (attachment, removal mechanism, external light connector, thickness of connector) - functioning & condition	81. Interior lighting - basic functioning, damage	131. IF FITTED: check the hand brake cables for integrity
- 32. Trunk - visual damage	82. Armrest - operation and condition	132. Check for audible signs of any issues while turning the wheel
33. Trunk - opening and holding mechanism	83. Front trims for condition	133. Check for signs of vibration on rear of the wheel while turning at speed (check during Testdrive if any indication of problems)
34. Automatic closure mechanism of trunk - functioning	84. Rear trims for condition	134. Check for signs of vibration on rear of the wheel while turning at speed (check during Testdrive if any indication of problems)
35. Integrity of rear bottom plate	85. Door trims for condition	135. Check the drive shaft covers for proper attachment and integrity (mainly tearing)
36. Fix new numberplate	86. Ceiling trims for condition	136. Check for slack on stub axles
37. Exterior mirrors - integrity of mirror itself and attachment to the car	87. Gear shift boot/skirt and Gear shift knob - condition	137. Check the attachement and integrity of stub axles covers
38. The state of the wheels	88. Parking brake for condition	138. Check for proper attachment and any slack
39. Check body panel geometry	89. Floor mats for condition	139. Check the integrity of the springs (mainly for breaks)
40. Car all along the left side - visual damage / scratches	90. Parcel shelf - operation and condition	140. Check the proper attachment of shock absorbers
 Car all along the right side - visual damage / scratches All 4 doors - proper opening and closing, handles working properly, etc. 	91. Carpets in luggage area - condition 92. Luggage compartment lights - functioning	141. Check leakage of shock absorbers142. Check the functioning of the shock absorbers while putting pressure
43. Battery capacity	93. Test drive (performed if there are any indications that test drive is	on the car 143. Check the engine mountings
	needed)	
44. Battery connectors - integrity and oxidation	94. OBD reading	144. Check the integrity and proper attachment of the fuel tank
45. Wiring integrity near battery	95. Satisfactory starting, general performance and the state of the vehicle	145. Check for potential fuel tank leaks
	96. Check key components for integrity and proper attachment: air intake system, radiator, main hoses, cables and connectors	146. Check for integrity of visible fuel lines (should not scrub against any part and should be properly fixed near fuel pump)
46. Battery properly fixed in the car		
	97. Check drive (V-) belt for integrity (cracks and dehydration signs)	147. Check the integrity and proper attachment of exhaust system
46. Battery properly fixed in the car 47. Alternator charging the battery (14.2 volt) 48. Locking mechanism on all doors and trunk including fuel hatch - functioning	97. Check drive (V-) belt for integrity (cracks and dehydration signs) 98. Check drive (V-) belt for tension	147. Check the integrity and proper attachment of exhaust system 148. Check for leakages all along the exhaust system
47. Alternator charging the battery (14.2 volt)48. Locking mechanism on all doors and trunk including fuel hatch -		

Diagnosis report of **2015 PEUGEOT 308 Executive** Stock ID: N941388