Diagnosis report of **2019 AUDI A3 S TRONIC**




Car Details

| Color: Black | CO ₂ NEDC Emission: 121 g/km |
|--|---|
| Fuel Type: Diesel | CO_2 WLTP Emission: 0 |
| Body Type: Hatchback | Low CO_2 Emissions: Yes |
| Number Of Doors: 4 | Engine size: 1.6 l |
| Number Of Seats: 5 | Cylinders: 4 |
| Mileage: 168 654 km | Power: 85 kw, 116 Hp |
| VIN Code: WAUZZZ8V9KA062380 | Fuel Consumption: 4.6 l/100km |
| Gearbox: Automatic | Tire size: 205/55 16 |
| Drive type: FWD | Longo Stock ID: L380149 |
| Next technical inspection date: 24.07.2024 | |
| | |

餐 Longo Certified

Car photos



Diagnosis report of **2019 AUDI A3 S TRONIC**



Diagnosis details

Date of completion: 17.07.2024

Mileage on completion date: 168 654 km

Checked by Longo Shared Service certified diagnostics: Arnas S., Mindaugas G., Agnius L.

This car has been thoroughly checked according to **Longo 150-point checklist** which covers Body exterior, Interior, and Mechanical condition. We can confirm that it has never been involved in major accidents and has had regular maintenance, as well as mandatory roadworthiness tests in the country of export.

Please note that certain general wear and tear issues are considered acceptable and may not be repaired.

Summary of diagnosed issues

During the comprehensive diagnosis conducted by Longo, 7 issues were identified in the vehicle. 5 of these issues were rectified. 2 of the diagnosed issues are deemed to be fair wear and tear.

| INTERIOR | EXTERIOR | MECHANICAL |
|-------------------|----------------------|----------------------|
| 1 issue rectified | 1 fair wear and tear | 4 issues rectified |
| | | I fair wear and tear |

Diagnosis process



Diagnosed issues repaired



Interior

- 1. FRONT: Window wash system functioning of front and back
 - Repair washer mechanism

Mechanical

1. OTHER:

Change the battery (in diagnosis)

2. OTHER:

Sensine oil & filter change

3. OTHER:

Regeneration

4. OTHER:

Charge the battery

Fair wear and tear



Exterior

1. REAR: Rear bumper - condition and alignment



Mechanical

1. GENERAL ELECTRICS: Glow plug relay

Longo 150-point checklist



Every vehicle is carefully examined according to Longo's comprehensive 150-point checklist, ensuring a thorough assessment of the car's interior, exterior, and mechanical condition. Depending on the factors such as condition, mileage, and specifications, additional checks may be included or certain points from the list may be omitted.

| Record the fuel type Record the transmission type A. Record the registration number S. Record the VIN number A. Record the mileage | 52. Check AdBlue level and add if necessary (only for diesel cars) 53. Check AdBlue level and add if necessary (only for diesel cars) 54. Check key - functioning and condition | 102. Check timing belt or chain for integrity 103. Check timing belt or chain for any audible signs of problems (start & while idling) 104. Check for any signs of leakage of any liquids |
|--|---|---|
| 4. Record the registration number 5. Record the VIN number | 54. Check key - functioning and condition | while idling) |
| 5. Record the VIN number | · - | 104. Check for any signs of leakage of any liquids |
| | | |
| 6. Record the mileage | 55. Check passenger chair airbag setting and reset to default | 105. Check level of coolant or anti-freeze in the tank |
| | 56. Dashboard - condition; operation of buttons | 106. Add coolant if necessary |
| 7. Record the year the car was manufactured | 57. Steering wheel - condition | 107. Check if coolant tank is filled with anti-freeze |
| 8. Record the date of first registration | 58. Steering wheel - operation of controls/buttons | 108. Ensure engine cooling system is free of visual contamination |
| 9. Record the date/mileage of the last service | 59. Car horn - operation | 109. Check quality of brake fluid using the testing pen |
| 10. Record the date/mileage of the next service due | 60. Window wipers (front & rear) - functioning | 110. Check the level of brake fluid |
| 11. Check car's maintenance history and manufacturer recall and safety campaigns | 61. Window wash system - functioning (front & rear) | 111. Check powersteering fluid color (if dark, replace) |
| 12. Front lights (city, regular and full headlight, fog, indicator) - functioning & condition | 62. Rearview mirror - operation and integrity of attachment | 112. Check powersteering fluid level |
| 13. Front light height adjustment system - functioning & condition | 63. Sunvisors - operation and condition | 113. Check oil level |
| 14. Lights on car sides - functioning & condition | 64. Rearview mirror - operation and integrity of attachment | 114. Check if tyres are properly fitted (should be fitted in driving direction |
| 15. Rear lights (brake, fog, indicator) - functioning & condition | 65. Headlining - condition | 115. Check tyre profile |
| 16. Numberplate lighting system - functioning & condition | 66. Roof items - electronic opening and condition | 116. Check tyre pressure |
| 201 Kamber plate lighting of stelling interestioning of condition | of Root Rents' cleen one opening and contactor | 117. Check the additional set of tyres - check for any signs of cracks due to |
| 17. Rear reflectors - condition | 67. Navigation and radio system - operation | dehydration (if there is an additional set of tyres) |
| Windscreen integrity - free from any damage that would exclude the vehicle from MOT test | 68. Rear view camera / proximity sensors - functioning | 118. Check additional set of tires - Check tire profile (if there is additional set of tires) |
| 19. Windscreen windows wiper rubbers and handles - condition | 69. Parking assistance systems - functioning | 119. Check the wheels for proper attachment (all bolts present and with correct tension) |
| 20. Front bumper - condition and alignment | 70. 12-volt and USB connectors - functioning | 120. Check the integrity and proper attachment of drivetrain system |
| 21. Front grill - condition | 71. Heating system - functioning | 121. Check the drivetrain attachment to engine for potential leaks |
| 22. Hood - visual damage | 72. Aircon system - functioning | 122. Check the integrity and the proper attachment of the wheelhouse |
| 23. Hood opening & holding mechanism | 73. Window heating mechanism - functioning (front & rear) | 123. Check the wheelhouse for potential leaks |
| 24. Hood sound insulation for condition | 74. Seat heating system - functioning (driver & passenger) | 124. Check for sings of slack while turning wheels to extreme position |
| 25. Fire wall for condition | 75. Seatbelts - functioning and locking mechanism | 125. Check the brake disks for integrity and potential oxidation |
| 26. Window washer fluid level (and adequate winter washer fluid) | 76. Seat adjustment mechanisms - functioning (driver & passenger) | 126. Check the brake pads for integrity and proper attachment |
| 27. Integrity of front subframe | 77. All seats - condition | 127. Check the brake pads for thickness |
| 28. Rear window integrity | 78. Door handles - operation and condition | 128. Check the integrity of brake hoses (signs of cracks from dehydration, misshaping and leakages) |
| 29. Rear windows wiper rubber and handle | 79. Electronic opening of all windows - functioning | 129. Check the integrity of brake pipes (oxydation, misshaping and leakages) |
| 30. Rear bumper - condition and alignment | 80. Exterior side mirrors - electronic mirror controls, folding and adjustment mechanism | 130. IF FITTED: check the brake drums for audible signs of any issues whil turning the wheels |
| 31. Tow hitch (attachment, removal mechanism, external light connector, thickness of connector) - functioning & condition | 81. Interior lighting - basic functioning, damage | 131. IF FITTED: check the hand brake cables for integrity |
| - 32. Trunk - visual damage | 82. Armrest - operation and condition | 132. Check for audible signs of any issues while turning the wheel |
| 33. Trunk - opening and holding mechanism | 83. Front trims for condition | 133. Check for signs of vibration on rear of the wheel while turning at speed (check during Testdrive if any indication of problems) |
| 34. Automatic closure mechanism of trunk - functioning | 84. Rear trims for condition | 134. Check for signs of vibration on rear of the wheel while turning at speed (check during Testdrive if any indication of problems) |
| 35. Integrity of rear bottom plate | 85. Door trims for condition | 135. Check the drive shaft covers for proper attachment and integrity (mainly tearing) |
| 36. Fix new numberplate | 86. Ceiling trims for condition | 136. Check for slack on stub axles |
| 37. Exterior mirrors - integrity of mirror itself and attachment to the car | 87. Gear shift boot/skirt and Gear shift knob - condition | 137. Check the attachement and integrity of stub axles covers |
| 38. The state of the wheels | 88. Parking brake for condition | 138. Check for proper attachment and any slack |
| | | |
| 39. Check body panel geometry | 89. Floor mats for condition | 139. Check the integrity of the springs (mainly for breaks) |
| 40. Car all along the left side - visual damage / scratches | 90. Parcel shelf - operation and condition | 140. Check the proper attachment of shock absorbers |
| Car all along the right side - visual damage / scratches All 4 doors - proper opening and closing, handles working properly, etc. | 91. Carpets in luggage area - condition 92. Luggage compartment lights - functioning | 141. Check leakage of shock absorbers142. Check the functioning of the shock absorbers while putting pressure |
| 43. Battery capacity | 93. Test drive (performed if there are any indications that test drive is | on the car 143. Check the engine mountings |
| | needed) | |
| 44. Battery connectors - integrity and oxidation | 94. OBD reading | 144. Check the integrity and proper attachment of the fuel tank |
| 45. Wiring integrity near battery | 95. Satisfactory starting, general performance and the state of the vehicle | 145. Check for potential fuel tank leaks |
| | 96. Check key components for integrity and proper attachment: air intake system, radiator, main hoses, cables and connectors | 146. Check for integrity of visible fuel lines (should not scrub against any part and should be properly fixed near fuel pump) |
| 46. Battery properly fixed in the car | | |
| | 97. Check drive (V-) belt for integrity (cracks and dehydration signs) | 147. Check the integrity and proper attachment of exhaust system |
| 46. Battery properly fixed in the car 47. Alternator charging the battery (14.2 volt) 48. Locking mechanism on all doors and trunk including fuel hatch - functioning | 97. Check drive (V-) belt for integrity (cracks and dehydration signs) 98. Check drive (V-) belt for tension | 147. Check the integrity and proper attachment of exhaust system 148. Check for leakages all along the exhaust system |
| 47. Alternator charging the battery (14.2 volt)48. Locking mechanism on all doors and trunk including fuel hatch - | | |

Diagnosis report of **2019 AUDI A3 S TRONIC** Stock ID: L380149